## Figure S1: Stepwise approach of handling an extravasation

Infusion/injection should be stopped; however, the needle must not be removed. One must first try to aspirate the solution from the tissue. It is also recommended to take a photo and to mark the extravasation/infiltration with a waterproof maker in order to measure and follow the extent of the event. Furthermore, the time of extravasation, estimated volume, location, and pain should be appropriately documented.

