

► Additional supplemental material is published online only. To view, please visit the journal online (http://dx. doi.org/10.1136/ejhpharm-2021-002747).

¹Department of Clinical Pharmacy, Zaans Medical Centre, Zaandam, The Netherlands ²Department of Clinical Pharmacy and Pharmacology, University Medical Centre Groningen, Groningen, The Netherlands ³Department of Clinical Pharmacy & Toxicology, Leiden University Medical Center, Leiden, The Netherlands ⁴Department of Clinical Pharmacy, Albert Schweitzer Ziekenhuis, Dordrecht, The Netherlands

Correspondence to

Frits A Boom, Zaans Medical Centre, 1502 DV Zaandam, The Netherlands; boom.f@ zaansmc.nl

Received 19 February 2021 Accepted 17 May 2021 Published Online First 7 July 2021

EAHP Statement 3: Production and Compounding.



http://dx.doi.org/10.1136/
 ejhpharm-2019-002178
 http://dx.doi.org/10.1136/
 ejhpharm-2019-002179

() Check for updates

© European Association of Hospital Pharmacists 2023. Re-use permitted under CC BY. Published by BMJ.

To cite: Boom FA, Le
Brun PPH, Ris JM, et al. Eur J Hosp Pharm
Eur J Hosp Pharm
2023; 30 :160–166.

160

Reducing the risk of non-sterility of aseptic handling in hospital pharmacies, part C: applying risk assessment and risk control in practice

Frits A Boom,^{1,2} Paul P H Le Brun,³ Judith M Ris,¹ Tjitske Veenbaas,⁴ Daan Touw²

ABSTRACT

Objectives To describe the application of the model described in part A and part B of this series of articles for risk assessment (RA) and risk control (RC) of non-sterility during aseptic handling. The model was applied in nine hospital pharmacies.

Methods The starting point was an audit of each hospital pharmacy. The determined risk reduction and remaining risks were entered into a risk assessment model. The corresponding risk prioritisation numbers (RPNs) for each source of risk were calculated and these values were summed up to a cumulative RPN. Subsequently, all hospital pharmacies started an improvement programme, using the risk assessment as input. Results of aseptic process simulation (APS) and microbiological monitoring (MM) were also collected. The participants were informed about their progress of risk reduction and results of APS and MM during the study period. At the end of the study (about 4 vears after the start), a final assessment was executed by using a checklist with risk reducing measures for each source of risk. Additional risk reduction and remaining risks were put in an RA and RC template and corresponding RPN values and a new cumulative RPN were determined.

Results At the start of the study differences in cumulative RPN values were relatively small (from 630 to 825). At the end they were relatively great (from 230 to 725), which illustrates a different sense of urgency for reducing the risk of non-sterility. Of all the risk reducing measures, a yearly audit of all operators had the greatest impact on reducing the risk of non-sterility. Except for glove prints, there was no correlation between process improvement (lower cumulative RPN) and results of microbiological controls.

Conclusion A systematic and science-based reduction of the risks of non-sterility can be done by using a checklist with risk reducing measures and an RA & RC template. Prospectively, the relevance of each risk reducing measure can be demonstrated by RPN calculations. Microbiological controls are an important part of the overall assurance of product quality. However, the results are less useful for assessing the risk of non-sterility.

INTRODUCTION

Aseptic handling is the procedure to enable sterile products to be made ready to administer using closed systems.¹ Because of the risk of medication errors and the chance of microbiological contamination during preparation, aseptic handling is recognised as a high-risk procedure.¹⁻³

In part A and part B of this series of articles we described a model for risk assessment (RA) and risk control (RC) of non-sterility during aseptic handling.^{4 5} Risk reducing measures, for each source of risk, were listed and remaining risks were quantified by using risk prioritisation numbers (RPNs). Nearly all sources of risk could be reduced to a safe level. However, touching critical spots as well as remaining micro-organisms after disinfection on stoppers or ampoule necks will still give a small risk of non-sterility. Besides, if aseptic handling is executed in a safety cabinet, the risk of blocking first air on critical spots cannot be completely excluded ('first air' and 'critical spot': definitions are given in online supplemental file 1).

The application of the developed RA and RC model and the effect of reducing the risk of nonsterility during aseptic handling in nine hospital pharmacies is described in this article. Implementation of risk reducing measures for each source of risk after an initial audit were tracked during a period of 4 years and evaluated after a final assessment. Results were expressed as a reduction of the RPN values.

In addition, if the chance of non-sterility has been reduced, better results of microbiological controls such as aseptic process simulation (APS) and microbiological monitoring (MM) are likely to be expected. Therefore, APS and MM were assessed as secondary outcomes.

The study focuses on non-hazardous products. However, most of the results and recommendations are also applicable to aseptic handling of hazardous products. There is only little experience with isolators in the Netherlands. Therefore, as in the previously published parts A and B, we restricted this study to aseptic handling done in a laminar airflow cabinet (LAF) or safety cabinet (SC).⁴⁵

MATERIALS AND METHODS Participating hospital pharmacies

Nine different kinds of hospital pharmacies (regional, top clinical and university) participated in this study. In these hospital pharmacies aseptic handling was carried out by well trained pharmaceutical technicians. Procedures are according to the chapter 'Aseptic handling of the Dutch GMP-hospital pharmacy'.⁶



Assessing aseptic handling in nine hospital pharmacies

The assessment of aseptic handling in the participating hospital pharmacies consisted of the following steps:

- 1. At the start of the study each hospital pharmacy was audited by an external pharmaceutical technician and an external hospital pharmacist as described in Part A.⁴ Risk reduction and remaining risks were entered into a risk assessment model, derived from figure 1 of part A. The corresponding RPN values for each source of risk were determined.
- 2. After this audit, each hospital pharmacy started an improvement programme, using the risk assessment as input. Results from APS and MM were also collected during the study period.
- 3. The participants were regularly informed about their progress in risk reduction and about the results of APS and MM of each participant.
- 4. At the end of the study (around 4 years after the start), a final assessment was executed by using a checklist with risk reducing measures for each source of risk. The description of the risk reducing measures was derived from figure 2, 3 and 4 of part B.⁵ The checklist was filled in by the principal investigator (F.A.B.) in consultation with the responsible staff.
- 5. The remaining risks and corresponding RPN value for each source of risk were determined by using an RA and RC template.

Microbiological controls

In all participating hospital pharmacies, the standard procedures for APS and MM, described by the Royal Dutch Pharmacists Association, have been used.^{7–9} APS is a broth simulation of the entire process and comprises all critical steps that occur during standard aseptic handling, by withdrawing a solution from a vial or ampoule, dissolving a powder in a vial and adding a solution to an infusion bag or vial. The broth solution used is Tryptone Soya Broth (TSB), Ph Eur. The final product is incubated for 14 days at 30°C and judged on either growth or no growth. The frequency is one APS preparation every working day.

The MM procedures are described in a condensed version in a previous article and consist of passive air sampling by settle plates, glove prints by 90 mm diameter agar plates and worktop prints by contact plates.⁸ The frequency is one sample of each kind of MM every working day.

Statistics

Contamination recovery rates (CRRs, a definition is given in online supplemental file 1) of MM were compared by p-values

using Fisher's exact test. For calculation of p-values, an online calculator was used.⁹

RESULTS

Participating hospital pharmacies

The study started with 10 hospital pharmacies, however in one pharmacy the production of non-hazardous products stopped. Therefore, the results from only nine hospital pharmacies were available for this study.

Table 1 is a short description of the participating hospital pharmacies. Some pharmacies produce a few thousand products each year (mainly parenteral nutrition), some produce more (up to nearly 100 000), for example if batches of syringes are filled or containers for portable infusion pump systems for outpatients are produced.

Assessing aseptic handling in nine hospital pharmacies

The risk assessment determined after the initial audit of hospital pharmacy 3 is shown in figure 1 (section 'risk assessment after initial audit'). The added up RPN value (cumulative RPN) is 780.

The complete checklist, which was used during the final assessment, is given in online supplemental file 2. An extract is given in figure 2. The checklist also gives an instruction for the final assessment.

If one of the risk reducing measures given in the checklist was implemented, the value(s) for O and/or D were reduced by the indicated number(s) of risk reduction in online supplemental file 2 and figure 2. For example, 'Worktop SC': a log for the registration of the daily disinfection of the worktop was introduced in hospital pharmacy 3 during the study period. This resulted in a reduction of D by one point (see figure 2, B: Worktop LAF/ SC). Another example, 'Critical spots (syringe tips, needles and the opening of tubes)': all additional risk reductions that were mentioned (see figure 2, D2: Critical spots), were implemented. O reduced by three points and D by two points.

Implemented risk reductions are indicated on the checklist. An example is given in online supplemental file 3 (this is the indicated checklist of hospital pharmacy 3). Additional risk reduction, remaining risk and the new values for O and D are entered into an RA and RC template as shown in figure 1 (section 'results after final assessment'). The cumulative RPN of hospital pharmacy 3 was reduced to 290 (see figure 1).

Table 2 contains the cumulative RPNs of all participating hospital pharmacies after the initial audit and after the final assessment. Table 2 also shows the implemented main additional risk reducing measures and an improvement ratio to express the

Table 1 Participa	ting hospital pharmacie	25		
Hospital number	Kind of hospital	Year cleanrooms constructed	Facilities and background area	Production 2019 (n)
1	Top clinical	2013	SC in grade C	4300
2	University	2012	SC in grade D	95 600
3	Top clinical	2008	SC in grade D	49500
4	Top clinical	1995/April 2019	SC in grade C	38400
5	Top clinical	2013	SC in grade C	15200
6	University	1981/November 2019	LAF in grade C	13700
7	Regional	2003	LAF in grade D	3200
8	Regional	2005	LAF in grade C	38 000
9	Regional	1986 /January 2017	LAF and SC in grade D	9800

Kind of hospital: regional, regional, regional hospital; top clinical, large hospital with a level and type of care similar to that offered by university hospitals; university, university hospital. Year cleanrooms constructed: if two dates are given, cleanrooms reconstructed during study period. Facilities and background area: background area; the room in which the LAF/SC is housed; grade C and grade D, EU grade C and grade D environment.²² Production 2019 (n): produced number of infusion bags, syringes, containers for portable infusion pump systems in 2019 (all non-hazardous products). LAF, laminar airflow cabinet; SC, safety cabinet.

Hospi	tal pharmacy 3	risk as	sessment after initial audit					results af	ter final assessment				
	sources of risk	risk reduction	remaining risk after first audit	s	0	D	R P 1 N	additional risk reduction	remaining risk	s	0		R P N :
Α	Air	SC checked once a year by particle measurements, airflow velocity and HEPA	1. chance of environment around work zone at rest not in accordance with Grade A air	5		2	10		chance of environment around work zone at rest not in accordance with Grade A air			2	10
		filter integrity in at rest condition; daily air sampling by settle plate	 materials and equipment disturb the unidirectional airflow and can block first air at critical spots 				30	no	materials and equipment disturb the unidirectional airflow and can block first air at critical spots	5	2	3	30
В	Worktop SC	disinfection before each work session by wiping with ethanol 70% impregnated wipes; daily monitoring by contact plate	1. disinfection forgotten; contamination by materials used during preparation				45	disinfection at the beginning of a working day is registered in a log	contamination by materials used during preparation still excists		3		
с	Wall and ceiling SC	daily surface disinfection by wiping with ethanol 70% impregnated wipes	1. disinfection forgotten		1		10	disinfection at the beginning of a working day is registered in a log	unlikely	5	1	1	5
	Materials with a sterile surface (sterile devices and infusion bags)	unwrapping in front of SC	1. contaminated outer layer		4		40	all operators in background area wear disposable gloves; original boxes are unpacked in front of lock with gloved hands; materials are used directly and/or stored in closed cupboards	transfer and storage is not audited		1		
					3		30	aseptic transfer is regularly audited and both operators correct each other	no aseptic transfer into SC by presentation		2		10
	Critical spots (syringe tips, needles and the opening of tubes)		1. contact of critical spots with the work top of SC	5	4	3	60	putting down syringes, needles and open tubes on a sterile pad in SC; use of sterile pad is regularly audited; both operators correct each other	unlikely	5	1	1	5
	Materials and equipment with a non- sterile surface	disinfection by wiping with ethanol 70% impregnated wipes	1. high surface bioburden before disinfection		3		45	ampoules and vials are transferred in their original boxes into the background area; materials are used directly and/or stored in closed cupboards	no periodical surface bioburden determination before disinfection; transfer and storage is not audited	5	1	3	15
	(ampoules, vials, bottles)		2. disinfection improperly done	5	4	4	80	thorough wiping by completely impregnated wipes; disinfection is regularly audited and both operators correct each other	no validated disinfection procedure; no regular surface monitoring of disinfected materials	5	2	3	30
			3. recontamination of disinfected materials	5	4	2	40	measures to prevent recontamination; measures to prevent changing disinfected and non-disinfected materials; measures are regularly audited and both operators correct each other	unlikely	5	1	1	5
	Critical spots (vial stoppers and ampoule necks)	additional disinfection in SC by wiping with sterile ethanol 70%	1. additional disinfection improperly done		3		60	precisely described and improved second disinfection technique; additional disinfection is regularly audited; both operators correct each other	still no assurance of a sterile surface		1		10
F	Operator's hands	sterile gloves, which are changed at least every hour; daily glove print by settle plate	1. glove damage		3		45	gloves integrity is tested immediately after putting them on and during processing; glove handling is regularly audited; both operators correct each other	unlikely		1		5
			2. surface contamination during putting on gloves		3		45	no	surface contamination during putting on gloves		3		45
			3. surface contamination during preparation		4		40	no	surface contamination during preparation		4		40
	Operator's forearm	wearing cleanroom clothing which is changed every day	1. surface contamination of the worktop		3		30	operator wears sterile sleeves which are changed after every session	unlikely		1		5
н	Working procedure	working with two operators during processing; SOPs; operators trained in aseptic techniques; aseptic process	1. deviation from SOPs		3		45	accurate and up to date SOPs (enough details, univocal text); working according to SOPs is regularly audited; both operators correct each other	unlikely		1		5
		simulation with a broth solution 2. touching critical spots 5 4 4 7					80	additional training in non-touch working; non-touch working is regularly audited; both operators correct each other	chance of touch still excists	5	2	2	20
			3. SC (downflow), blocking first air at critical spots	5	3	3	45	prevention of blocking first air is regularly audited; both operators correct each other	chance of blocking first air still excists	5	2	1	10

Figure 1 Completed RA and RC template after the final assessment of hospital pharmacy 3. 780, cumulative RPN after the initial audit; 290, cumulative RPN after the final assessment; D, detection; O, occurrence; RPN, risk prioritisation number; S, severity.

relative risk reduction of each participant. Online supplemental file 4 contains the completed RA and RC templates of all participating hospital pharmacies.

Microbiological controls

APS results are expressed in contamination rates, which means the percentage of samples with growth. The results are

B: Worktop LAF/SC

Risk reduction: Disinfection before each work session by wiping with ethanol or isopropyl alcohol 70% impregnated wipes; daily monitoring by contact plate.

Remaining risk	0	D
Disinfection forgotten; contamination by materials used during preparation. Additional risk reduction:		
Disinfection at the beginning of a working day is registered in a log.		-1
Disinfection before each new prepared dosage form.	-1	
Disinfection before each new prepared dosage form is regularly audited.	-1	-1

D2: Critical spots (syringe tips, needles and the opening of tubes)

Remaining risk	0	D
1. Contact of critical spots with the work top of LAF/SC.		
Additional risk reduction:		
Putting down syringes, needles and open tubes on a sterile pad in	-2	
LAF/SC.		
Use of sterile pad is regularly audited.	-1	-1
Both operators correct each other.		-1

Figure 2 An extract of the checklist with risk reducing measures; the complete checklist is given in online supplemental file 2. Risk reduction and remaining risk, listed in the checklist, were the mean results after the initial audits in the nine participating hospital pharmacies. D, detection; LAF, laminar airflow cabinet; O, occurrence; SC, safety cabinet.

summarised in table 3. Hospital pharmacies 6 and 7 had one sample with growth (2019 and 2016, respectively). The seven other hospital pharmacies had no growth during the study period.

MM results, expressed as CRR, are given in tables 4 and 5. They are derived from the LAF/SC most used in each hospital pharmacy. CRR results above 10% (the limit used in the Netherlands) appear in bold.¹⁰ To calculate reliable values for CRR, only results of 100 or more samples a year are given in tables 4 and $5.^{8}$

The results of air and worktop sampling did not change substantially during the study period (see table 4). Therefore, further statistical calculations for these results were not performed.

The results of glove prints from the start of the study (2016) and the end of the study (2019) were compared by Fisher's exact test. The results of hospital pharmacies 5 and 6 show a statistically significant improvement. The results of hospital pharmacy 9 also show a statistically significant difference. However, 2016 must be considered as a year with extremely low results (see table 5; before 2016, CRRs were 5.76% and 5.71% in 2014 and 2015, respectively).

DISCUSSION

Participating hospital pharmacies

There is no correlation between the results (cumulative RPNs as well as microbiological controls) and the kind of hospital, nor between the results and the age of the cleanrooms. Hospital pharmacies 1 and 9 had the overall best results at the end of the study (see tables 2 and 5).

0	rigi	nal	research

Eur J Hosp Pharm: first published as 10.1136/ejhpharm-2021-002747 on 7 July 2021. Downloaded from http://ejhp.bmj.com/ on April 19, 2024 by guest. Protected by copyright

Ampoules and vials Hands and foream of the operator Working proced working working working working working mipproved working working working disinfection disinfection disinfection working disinfection disinfection disinfection technique disinfection disinfection disinfection disinfection technique disinfection disinfection additional disinfection disinfection technique disinfection feever technique filteretion disinfection disinfection disinfection technique disinfection disinfection disinfection disinfection disinfection disinfection technique disinfection disinfection disinfection disinfection disinfection disinfection disinfection technique disinfection disinfection disinfection disinfection disinfection disinfection technique technique disinfecti	Image: sector of the	Start							Main	n additional ris	k reduction fo	Main additional risk reduction for each source of risk at the end of the study	of risk at the e	nd of the study								End	
Matche in the formation of the for	Model Model <th< th=""><th></th><th></th><th>Air</th><th></th><th>Worktop, wa</th><th>alls, ceiling</th><th>SMD</th><th></th><th></th><th>A</th><th>mpoules and v</th><th>ials</th><th></th><th>Hand</th><th>ds and forear</th><th>n of the opera</th><th>ator</th><th>Worl</th><th>king procedur</th><th></th><th>umulative (PN RPN2)</th><th>lmprovemen ratio (RPN2/ RPN1)</th></th<>			Air		Worktop, wa	alls, ceiling	SMD			A	mpoules and v	ials		Hand	ds and forear	n of the opera	ator	Worl	king procedur		umulative (PN RPN2)	lmprovemen ratio (RPN2/ RPN1)
$ \begin{array}{llllllllllllllllllllllllllllllllllll$	10 + 1			ate		Disinfection registered in a log	Increased frequency worktop disinfection	e e	. a	Low surface bioburden before disinfection	Improved disinfection technique	Validated disinfection technique	Monitoring after disinfection	Improved additional disinfection of critical spots	Check of glove damage	Good putting on technique	Glove disinfection before start and every 15 min			e .	revention if blocking irst air is a najor topic luring udits		
$ \begin{array}{cccccccccccccccccccccccccccccccccccc$	70 -	740	+			+	+			+	+	I	I	+	+	+	+					30	0.31
$ \begin{array}{cccccccccccccccccccccccccccccccccccc$	30 $+$ $ +$ $+$ </td <td></td> <td>I</td> <td></td> <td></td> <td>+</td> <td>1</td> <td>I</td> <td></td> <td></td> <td>1</td> <td>I</td> <td>1</td> <td>1</td> <td></td> <td>+</td> <td>1</td> <td></td> <td></td> <td></td> <td></td> <td>00</td> <td>0.95</td>		I			+	1	I			1	I	1	1		+	1					00	0.95
825 + +* + </td <td>82 $+$ $+$<!--</td--><td></td><td>+</td><td></td><td></td><td>+</td><td>I</td><td></td><td></td><td>+</td><td>+</td><td>I</td><td>I</td><td>+</td><td>+</td><td>I</td><td>I</td><td></td><td></td><td></td><td></td><td>06</td><td>0.37</td></td>	82 $+$ </td <td></td> <td>+</td> <td></td> <td></td> <td>+</td> <td>I</td> <td></td> <td></td> <td>+</td> <td>+</td> <td>I</td> <td>I</td> <td>+</td> <td>+</td> <td>I</td> <td>I</td> <td></td> <td></td> <td></td> <td></td> <td>06</td> <td>0.37</td>		+			+	I			+	+	I	I	+	+	I	I					06	0.37
$\begin{array}{cccccccccccccccccccccccccccccccccccc$	75+-++++++ 280 820 +++++ 40 21 20 75 +++ 41 <td></td> <td>+</td> <td></td> <td></td> <td>+</td> <td>+</td> <td>+</td> <td></td> <td>1</td> <td>+</td> <td>I</td> <td>1</td> <td>I</td> <td>++</td> <td>I</td> <td>#</td> <td></td> <td></td> <td></td> <td></td> <td>65</td> <td>0.44</td>		+			+	+	+		1	+	I	1	I	++	I	#					65	0.44
$ \begin{array}{cccccccccccccccccccccccccccccccccccc$	820 $ +$ $+$ $+$ $+$ $+$ $+$ $+$ $+$ $+$ $ 50$ 50		+			+	+	I		+	+	+	I	+	1	+	+					80	0.35
795 - - + - - - - + - + - + -	75 $ -$		I			+	+			+	+	+	I	+	1	+	I					05	0.62
 * *<	+ - + + + + + 280 + + + + + + + + 231 + + + + + + + + + 235 - - + + + + + + + 235	795	I			+	1	I		1	I	I	1	I	1	I	1					25	0.91
* * * * * *	+ + + + + + 235	760	+			+	+			+	+	I	+	+	+	+	+					80	0.37
additional risk reduction implemented:, additional risk reduction not implemented ontinous sparite counting coule glowed sharked for Started at the end of 2019.	additional risk reduction implemented. The contropy of the con	630	+			+	+				+	+	+	+	+	+	+					35	0.37
d, cumulative RPN after the final assessment, RPN, risk prioritisation number; SMD, sterile medical device; Start, cumulative RPN after the initial audit.		additional risk reduct continuous particle co bouble gloved hands requent glove disinfec dd, cumulative RPN aft	tion implemented; –, a unting ±ion started at the env er the final assessmen	ldditional risk reducti 1 of 2019. 1t, RPN, risk prioritisa	ion not implemen tion number; SMI	nted. D, sterile medical d	levice; Start, cumula	ative RPN after th	te initial audi														

 Table 3
 Results of aseptic process simulation (APS) in nine hospital
 oharmacies

	2	2016	2	2017	2	018		2019
Hospital number	n	CR (%)	n	CR (%)	n	CR (%)	n	CR (%)
1	115	0	117	0	95	0	195	0
2	421	0	309	0	355	0	313	0
3	391	0	414	0	445	0	458	0
4	216	0	227	0	242	0	310	0
5	91	0	93	0	131	0	136	0
6	945	0	987	0	1015	0.1	955	0
7	195	0.51	160	0	246	0	169	0
8	Х	х	96	0	501	0	461	0
9	277	0	384	0	284	0	310	0
Results with	growth ap	pear in bol	d.					

R, contamination rate; hospital number, hospital pharmacy number in this study; n, number of amples examined: x. data not available

omments on the risk reduction of the different sources of risk

n this section comments and additional information about risk eduction of the different sources of risk are given.

ir

Aost hospital pharmacies own a particle counter, but only one id quarterly non-viable particle counting at rest around the vork zone ('at rest' and 'work zone': definitions are given in nline supplemental file 1); this lack of counting is a shame ecause non-viable particle counting is a simple experiment, hile the results will give valuable information about complying vith the at rest criteria for airborne particles.⁵

In hospital pharmacies 1, 8 and 9, videos about the risk of locking first air by materials were used to find the correct posion of materials inside LAF/SC.¹¹

The results of viable air sampling are already far below the 4M limits of up to 10% at the start of the study and did not eally change during the study period (see table 4). This is not urprising because there are no distinct sources to contaminate he air inside LAF/SC.⁵

Vorktop, walls and ceiling of LAF/SC

n all hospital pharmacies, except numbers 2, 3 and 7, the requency of worktop disinfection increased (see table 2). lowever, the expected decrease of the CRRs of the worktop rints could not be assessed because the number of samples as often too low to get reliable CRR values (marked as 'x' in ble 4).⁸ But a positive outcome was the number of pharmacies

Table 4	Results of air sampling and worktop prints in nine hospital
pharmac	es

Hospital		CRI	R air (%)			CRR wo	orktop (%)
number	2016	2017	2018	2019	2016	2017	2018	2019
1	1.15	1.60	0.27	1.17	2.34	0.80	2,61	0.88
2	5.56	7.19	3.35	5.19	3.59	4.10	4.51	3.29
3	2.14	0.63	1.14	2.03	х	х	х	х
4	4.94	2.94	6.47	1.95	2.72	1.68	1.32	2.62
5	1.38	3.19	3.36	0.88	х	х	6.36	5.67
6	5.84	7.53	5.85	2.73	х	х	х	2.55
7	0.76	0.67	0.52	3.35	х	х	х	3.13
8	3.94	4.73	3.00	2.40	х	х	х	Х
9	0.00	0.34	0.81	0.78	3.99	1.01	0.00	1.57
CRR, contamin not enough da					number in th	is study; x, o	data not ava	ailable or

					•	rmacies										
		2016				2017				2018				2	019	
n	pos	neg	CRR (%)	n	pos	neg	CRR (%)	n	pos	neg	CRR (%)	n	pos	neg	CRR (%)	p value
390	5	385	1.28	376	13	363	3.46	361	8	353	2.22	349	5	344	1.43	1
215	12	203	5.58	146	13	133	8.90	244	15	229	6.15	220	24	196	10.91	0.0549
882	42	840	4.76	790	34	756	4.30	784	24	760	3.06	727	35	692	4.81	1
157	23	134	14.65	129	21	108	16.28	162	27	135	16.67	208	35	173	17.24	0.6648
290	39	251	13.45	226	23	203	10.18	299	21	278	7.02	452	37	415	8.19	0.0253
585	99	486	16.92	623	109	514	17.50	517	76	441	14.70	1231	92	1139	7.47	0.0001
132	10	122	7.58	120	16	104	13.33	194	8	186	4.12	179	16	163	8.94	0.8362
501	64	437	12.77	493	56	437	11.36	603	48	555	7.96	637	60	577	9.42	0.0843
294	5	289	1.70	298	13	285	4.36	246	8	238	3.25	255	13	242	5.10	0.0307
	390 215 882 157 290 585 132 501 294	390 5 215 12 882 42 157 23 290 39 585 99 132 10 501 64 294 5	390 5 385 215 12 203 882 42 840 157 23 134 290 39 251 585 99 486 132 10 122 501 64 437	390 5 385 1.28 215 12 203 5.58 882 42 840 4.76 157 23 134 14.65 290 39 251 13.45 585 99 486 16.92 132 10 122 7.58 501 64 437 12.77 294 5 289 1.70	390 5 385 1.28 376 215 12 203 5.58 146 882 42 840 4.76 790 157 23 134 14.65 129 290 39 251 13.45 226 585 99 486 16.92 623 132 10 122 7.58 120 501 64 437 12.77 493 294 5 289 1.70 298	390 5 385 1.28 376 13 215 12 203 5.58 146 13 882 42 840 4.76 790 34 157 23 134 14.65 129 21 290 39 251 13.45 226 23 585 99 486 16.92 623 109 132 10 122 7.58 120 16 501 64 437 12.77 493 56 294 5 289 1.70 298 13	390 5 385 1.28 376 13 363 215 12 203 5.58 146 13 133 882 42 840 4.76 790 34 756 157 23 134 14.65 129 21 108 290 39 251 13.45 226 23 203 585 99 486 16.92 623 109 514 132 10 122 7.58 120 16 104 501 64 437 12.77 493 56 437 294 5 289 1.70 298 13 285	390 5 385 1.28 376 13 363 3.46 215 12 203 5.58 146 13 133 8.90 882 42 840 4.76 790 34 756 4.30 157 23 134 14.65 129 21 108 16.28 290 39 251 13.45 226 23 203 10.18 585 99 486 16.92 623 109 514 17.50 132 10 122 7.58 120 16 104 13.33 501 64 437 12.77 493 56 437 11.36 294 5 289 1.70 298 13 285 4.36	390 5 385 1.28 376 13 363 3.46 361 215 12 203 5.58 146 13 133 8.90 244 882 42 840 4.76 790 34 756 4.30 784 157 23 134 14.65 129 21 108 16.28 162 290 39 251 13.45 226 23 203 10.18 299 585 99 486 16.92 623 109 514 17.50 517 132 10 122 7.58 120 16 104 13.33 194 501 64 437 12.77 493 56 437 11.36 603 294 5 289 1.70 298 13 285 4.36 246	390 5 385 1.28 376 13 363 3.46 361 8 215 12 203 5.58 146 13 133 8.90 244 15 882 42 840 4.76 790 34 756 4.30 784 24 157 23 134 14.65 129 21 108 16.28 162 27 290 39 251 13.45 226 23 203 10.18 299 21 585 99 486 16.92 623 109 514 17.50 517 76 132 10 122 7.58 120 16 104 13.33 194 8 501 64 437 12.77 493 56 437 11.36 603 48 294 5 289 1.70 298 13 285 4.36 246 8 <td>390 5 385 1.28 376 13 363 3.46 361 8 353 215 12 203 5.58 146 13 133 8.90 244 15 229 882 42 840 4.76 790 34 756 4.30 784 24 760 157 23 134 14.65 129 21 108 16.28 162 27 135 290 39 251 13.45 226 23 203 10.18 299 21 278 585 99 486 16.92 623 109 514 17.50 517 76 441 132 10 122 7.58 120 16 104 13.33 194 8 186 501 64 437 12.77 493 56 437 11.36 603 48 555 294 5<!--</td--><td>390 5 385 1.28 376 13 363 3.46 361 8 353 2.22 215 12 203 5.58 146 13 133 8.90 244 15 229 6.15 882 42 840 4.76 790 34 756 4.30 784 24 760 3.06 157 23 134 14.65 129 21 108 16.28 162 27 135 16.67 290 39 251 13.45 226 23 203 10.18 299 21 278 7.02 585 99 486 16.92 623 109 514 17.50 517 76 441 14.70 132 10 122 7.58 120 16 104 13.33 194 8 186 4.12 501 64 437 12.77 493 56</td><td>390 5 385 1.28 376 13 363 3.46 361 8 353 2.22 349 215 12 203 5.58 146 13 133 8.90 244 15 229 6.15 220 882 42 840 4.76 790 34 756 4.30 784 24 760 3.06 727 157 23 134 14.65 129 21 108 16.28 162 27 135 16.67 208 290 39 251 13.45 226 23 203 10.18 299 21 278 7.02 452 585 99 486 16.92 623 109 514 17.50 517 76 441 14.70 1231 132 10 122 7.58 120 16 104 13.33 194 8 186 4.12 179</td><td>390 5 385 1.28 376 13 363 3.46 361 8 353 2.22 349 5 215 12 203 5.58 146 13 133 8.90 244 15 229 6.15 220 24 882 42 840 4.76 790 34 756 4.30 784 24 760 3.06 727 35 157 23 134 14.65 129 21 108 16.28 162 27 135 16.67 208 35 290 39 251 13.45 226 23 203 10.18 299 21 278 7.02 452 37 585 99 486 16.92 623 109 514 17.50 517 76 441 14.70 1231 92 132 10 122 7.58 120 16 104 <t< td=""><td>390 5 385 1.28 376 13 363 3.46 361 8 353 2.22 349 5 344 215 12 203 5.58 146 13 133 8.90 244 15 229 6.15 220 24 196 882 42 840 4.76 790 34 756 4.30 784 24 760 3.06 727 35 692 157 23 134 14.65 129 21 108 16.28 162 27 135 16.67 208 35 173 290 39 251 13.45 226 23 203 10.18 299 21 278 7.02 452 37 415 585 99 486 16.92 623 109 514 17.50 517 76 441 14.70 1231 92 1139 132</td><td>390 5 385 1.28 376 13 363 3.46 361 8 353 2.22 349 5 344 1.43 215 12 203 5.58 146 13 133 8.90 244 15 229 6.15 220 24 196 10.91 882 42 840 4.76 790 34 756 4.30 784 24 760 3.06 727 35 692 4.81 157 23 134 14.65 129 21 108 16.28 162 27 135 16.67 208 35 173 17.24 290 39 251 13.45 226 23 203 10.18 299 21 278 7.02 452 37 415 8.19 585 99 486 16.92 623 109 514 17.50 517 76 441 14.70</td></t<></td></td>	390 5 385 1.28 376 13 363 3.46 361 8 353 215 12 203 5.58 146 13 133 8.90 244 15 229 882 42 840 4.76 790 34 756 4.30 784 24 760 157 23 134 14.65 129 21 108 16.28 162 27 135 290 39 251 13.45 226 23 203 10.18 299 21 278 585 99 486 16.92 623 109 514 17.50 517 76 441 132 10 122 7.58 120 16 104 13.33 194 8 186 501 64 437 12.77 493 56 437 11.36 603 48 555 294 5 </td <td>390 5 385 1.28 376 13 363 3.46 361 8 353 2.22 215 12 203 5.58 146 13 133 8.90 244 15 229 6.15 882 42 840 4.76 790 34 756 4.30 784 24 760 3.06 157 23 134 14.65 129 21 108 16.28 162 27 135 16.67 290 39 251 13.45 226 23 203 10.18 299 21 278 7.02 585 99 486 16.92 623 109 514 17.50 517 76 441 14.70 132 10 122 7.58 120 16 104 13.33 194 8 186 4.12 501 64 437 12.77 493 56</td> <td>390 5 385 1.28 376 13 363 3.46 361 8 353 2.22 349 215 12 203 5.58 146 13 133 8.90 244 15 229 6.15 220 882 42 840 4.76 790 34 756 4.30 784 24 760 3.06 727 157 23 134 14.65 129 21 108 16.28 162 27 135 16.67 208 290 39 251 13.45 226 23 203 10.18 299 21 278 7.02 452 585 99 486 16.92 623 109 514 17.50 517 76 441 14.70 1231 132 10 122 7.58 120 16 104 13.33 194 8 186 4.12 179</td> <td>390 5 385 1.28 376 13 363 3.46 361 8 353 2.22 349 5 215 12 203 5.58 146 13 133 8.90 244 15 229 6.15 220 24 882 42 840 4.76 790 34 756 4.30 784 24 760 3.06 727 35 157 23 134 14.65 129 21 108 16.28 162 27 135 16.67 208 35 290 39 251 13.45 226 23 203 10.18 299 21 278 7.02 452 37 585 99 486 16.92 623 109 514 17.50 517 76 441 14.70 1231 92 132 10 122 7.58 120 16 104 <t< td=""><td>390 5 385 1.28 376 13 363 3.46 361 8 353 2.22 349 5 344 215 12 203 5.58 146 13 133 8.90 244 15 229 6.15 220 24 196 882 42 840 4.76 790 34 756 4.30 784 24 760 3.06 727 35 692 157 23 134 14.65 129 21 108 16.28 162 27 135 16.67 208 35 173 290 39 251 13.45 226 23 203 10.18 299 21 278 7.02 452 37 415 585 99 486 16.92 623 109 514 17.50 517 76 441 14.70 1231 92 1139 132</td><td>390 5 385 1.28 376 13 363 3.46 361 8 353 2.22 349 5 344 1.43 215 12 203 5.58 146 13 133 8.90 244 15 229 6.15 220 24 196 10.91 882 42 840 4.76 790 34 756 4.30 784 24 760 3.06 727 35 692 4.81 157 23 134 14.65 129 21 108 16.28 162 27 135 16.67 208 35 173 17.24 290 39 251 13.45 226 23 203 10.18 299 21 278 7.02 452 37 415 8.19 585 99 486 16.92 623 109 514 17.50 517 76 441 14.70</td></t<></td>	390 5 385 1.28 376 13 363 3.46 361 8 353 2.22 215 12 203 5.58 146 13 133 8.90 244 15 229 6.15 882 42 840 4.76 790 34 756 4.30 784 24 760 3.06 157 23 134 14.65 129 21 108 16.28 162 27 135 16.67 290 39 251 13.45 226 23 203 10.18 299 21 278 7.02 585 99 486 16.92 623 109 514 17.50 517 76 441 14.70 132 10 122 7.58 120 16 104 13.33 194 8 186 4.12 501 64 437 12.77 493 56	390 5 385 1.28 376 13 363 3.46 361 8 353 2.22 349 215 12 203 5.58 146 13 133 8.90 244 15 229 6.15 220 882 42 840 4.76 790 34 756 4.30 784 24 760 3.06 727 157 23 134 14.65 129 21 108 16.28 162 27 135 16.67 208 290 39 251 13.45 226 23 203 10.18 299 21 278 7.02 452 585 99 486 16.92 623 109 514 17.50 517 76 441 14.70 1231 132 10 122 7.58 120 16 104 13.33 194 8 186 4.12 179	390 5 385 1.28 376 13 363 3.46 361 8 353 2.22 349 5 215 12 203 5.58 146 13 133 8.90 244 15 229 6.15 220 24 882 42 840 4.76 790 34 756 4.30 784 24 760 3.06 727 35 157 23 134 14.65 129 21 108 16.28 162 27 135 16.67 208 35 290 39 251 13.45 226 23 203 10.18 299 21 278 7.02 452 37 585 99 486 16.92 623 109 514 17.50 517 76 441 14.70 1231 92 132 10 122 7.58 120 16 104 <t< td=""><td>390 5 385 1.28 376 13 363 3.46 361 8 353 2.22 349 5 344 215 12 203 5.58 146 13 133 8.90 244 15 229 6.15 220 24 196 882 42 840 4.76 790 34 756 4.30 784 24 760 3.06 727 35 692 157 23 134 14.65 129 21 108 16.28 162 27 135 16.67 208 35 173 290 39 251 13.45 226 23 203 10.18 299 21 278 7.02 452 37 415 585 99 486 16.92 623 109 514 17.50 517 76 441 14.70 1231 92 1139 132</td><td>390 5 385 1.28 376 13 363 3.46 361 8 353 2.22 349 5 344 1.43 215 12 203 5.58 146 13 133 8.90 244 15 229 6.15 220 24 196 10.91 882 42 840 4.76 790 34 756 4.30 784 24 760 3.06 727 35 692 4.81 157 23 134 14.65 129 21 108 16.28 162 27 135 16.67 208 35 173 17.24 290 39 251 13.45 226 23 203 10.18 299 21 278 7.02 452 37 415 8.19 585 99 486 16.92 623 109 514 17.50 517 76 441 14.70</td></t<>	390 5 385 1.28 376 13 363 3.46 361 8 353 2.22 349 5 344 215 12 203 5.58 146 13 133 8.90 244 15 229 6.15 220 24 196 882 42 840 4.76 790 34 756 4.30 784 24 760 3.06 727 35 692 157 23 134 14.65 129 21 108 16.28 162 27 135 16.67 208 35 173 290 39 251 13.45 226 23 203 10.18 299 21 278 7.02 452 37 415 585 99 486 16.92 623 109 514 17.50 517 76 441 14.70 1231 92 1139 132	390 5 385 1.28 376 13 363 3.46 361 8 353 2.22 349 5 344 1.43 215 12 203 5.58 146 13 133 8.90 244 15 229 6.15 220 24 196 10.91 882 42 840 4.76 790 34 756 4.30 784 24 760 3.06 727 35 692 4.81 157 23 134 14.65 129 21 108 16.28 162 27 135 16.67 208 35 173 17.24 290 39 251 13.45 226 23 203 10.18 299 21 278 7.02 452 37 415 8.19 585 99 486 16.92 623 109 514 17.50 517 76 441 14.70

Results above the 10% limit are in bold.

CRR, contamination recovery rate; n, number of samples examined; neg, number of samples without growth; hospital number, hospital pharmacy number in this study; pos, number of samples with one or more cfu; p value, CRR 2019 compared with CRR 2016.

where daily monitoring of the worktop was being implemented at the end of the study (increased from four to seven hospitals; see table 4).

Materials with a sterile surface (sterile medical devices)

Even after thorough disinfection, the worktop has to be considered as a non-sterile surface. Therefore, a sterile pad is advised to prevent contact between critical spots (syringe tips, needles, openings of tubes) and the surface of the worktop.¹² By the end of the study this pad was being used in four hospital pharmacies (see table 2). An alternative is to put syringes and needles on a sterile holder. Online supplemental file 5 gives an example.

Materials with a non-sterile surface (ampoules and vials)

Hospital pharmacies 5, 6 and 9 implemented the validated twotowel disinfection technique by using commercially available impregnated sterile polypropylene wipes.¹³ The two-towel technique was also introduced in hospital pharmacies 1 and 8, but these hospital pharmacies used cotton gauzes or medical nonwoven wipes, submerged in alcohol 70%. Compared with the commercially available polypropylene wipes, these gauzes and wipes are less expensive. However, a disadvantage of cotton or medical non-woven is the higher emission of particles and fibers. Hospital pharmacies 3 and 4 also improved the disinfection technique (see online supplemental file 4).

Dragging microorganisms across materials with a non-sterile surface is a serious risk.⁴ Therefore, regular surface monitoring after disinfection is strongly advised.^{13–15} This has been implemented in hospital pharmacies 8 and 9 (see table 2). A procedure for routine monitoring of materials with a non-sterile surface is described by Boom and colleagues.¹⁶

Operator's hands

This section refers to the hands of the primary operator (a definition of which is given in online supplemental file 1). The MM results of glove prints improved during the study period (see table 4). In addition, the frequent glove disinfection which started at the end of 2019 in hospital pharmacy 4 also led to results below the limit of 10% in the next year. Better results for glove prints are not only the result of more frequent glove disinfection, but also the result of more frequent worktop disinfection and better disinfection of materials with a non-sterile surface.⁵ However, if all these improvements are not implemented, a result below the MM limit of up to 10% is also possible (see figure 2, hospital pharmacy 7). Possible explanations for this

finding are a low surface bioburden of materials and/or concurrent disinfection of the gloves by the impregnated wipes used during the disinfection of materials and/or frequent glove changes. Besides, the technique of performing glove prints itself can have a great influence on the results.^{8 17} Contact time that is too short, for instance, as well as a too small printed surface of the distal phalanx of the fingers, will have a negative influence on the recovery and therefore on the results.

Operator's forearm

This section refers to the forearm of the primary operator. At the end of the study sterile sleeves were used in five hospital pharmacies. As mentioned in part B, sterile long-sleeved gloves will give the same protection as separate sterile gloves and sleeves.⁵

Working procedure

During the whole study period all contamination rates after APS are very low (see table 3). These results show, despite possibilities for risk reduction, that the operators were capable of producing products with a low chance of microbial contamination. However, a few remarks about these results can be made. First, during aseptic handling sometimes the preparation time is longer, and the number of preparation steps is larger compared with the usual applied broth simulation. Therefore, APS is not always a worst case simulation. Second, a more precise way of working during APS, compared with 'normal' aseptic handling, is not inconceivable. Third, not all aspects of the way of working can be measured by APS.¹⁸

In this connection, we emphasise the importance of a yearly audit of all operators as well as stimulating a policy of correcting each other. This not only has a great influence on risk reduction of working procedures, but also on many other sources of risk (see checklist in online supplemental file 2). At the end of the study auditing has been implemented in six hospital pharmacies (see table 2). More information about auditing can be found in part B.⁵

As mentioned in part A, two operators working together during processing is strongly recommended⁴; it makes a policy of correcting each other more workable as well as dividing activities that occur outside and inside LAF/SC and transferring materials into LAF/SC. All hospital pharmacies, except numbers 6, 8 and 9, were already working with two operators during processing at the start of the study. This did not change during the study.

Reducing the risk of non-sterility in nine hospital pharmacies

The cumulative RPN values at the start of the study varied from 630 to 825 (table 2). At the end of the study the differences were much greater, which leads to a cumulative RPN variation of 230 to 725 (see table 2). The improvement ratios also show great differences (see table 2). A sense of urgency and the time available for the implementation of the additional risk reducing measures are the main reasons for these differences. To enforce process changes, involvement of the responsible staff and the operators is an essential precondition. To enhance this, some hospital pharmacies work with a lean board and stand-up sessions and/or stimulate a policy to correct each other during operation. Additionally, for observing follow-up activities, it is important to use a system for corrective and preventive actions.¹⁹

Microbiological controls are an important part of the overall assurance of product quality.²⁰ Unfortunately, except for glove prints, we did not find a correlation between process improvement (lower cumulative RPN) and the results of microbiological controls. Explanations are given in the subsections above.

It is well known that microbiological controls alone will not cover all sources of risk of non-sterility.¹⁸ Therefore, according to the principles of a pharmaceutical quality system, it is necessary to evaluate all these sources.²¹ The relevance of each, in combination with the effort to reduce them, can be made clear by the RA and RC model, described in parts A and B.^{4.5}

Obviously, the implementation of the risk reducing measures will take time and/or will involve expense. For example, having an audit of two operators requires about 4 hours' work by the auditor.⁵ However, various measures can be implemented by only changing the way of working, without loss of productivity (for example, working without blocking first air on critical spots). Of course, a change itself will take time and energy, but a more robust process is a valuable result. Some measures will even save time, like transfer of ampoules and injection vials in their original white cardboard boxes into the background area (a definition of which is given in online supplemental file 1). This way of working keeps the surface bioburden of ampoules and vials low and shows no measurable influence on the particle burden in the background area.¹²

Application of risk assessment can also cast doubt on habits that have become general practice after years and years. For example, in previous articles we made clear that viable air sampling inside LAF/SC is not sensitive enough for controlling the environment inside LAF/SC or for detecting a filter failure.^{5 8} Therefore, based on the principles of risk assessment, discontinuation of this MM method is a serious option.

Assessing aseptic handling in other hospital pharmacies

Assessing aseptic handling in other hospital pharmacies can also be done with the checklist available in online supplemental file 2. As mentioned above, an instruction for the assessment is given in the checklist. For determining the RPN values and the remaining risk, a 'blank' RA and RC template is available in online supplemental file 6.

The determined RPN values can be used for prioritising additional measures for risk reduction. RPN values over 30 are called 'not safe' (red) and must be reduced first.⁴

CONCLUSION

Systematic and science-based reduction of the risks of non-sterility can be done by using a checklist with risk reducing measures and an RA and RC template. Prospectively, the relevance of each risk reducing measure can be demonstrated by RPN calculations. Of all risk reducing measures, a yearly audit of all operators has the greatest impact on reducing the risk of non-sterility. Microbiological controls are an important part of the overall assurance of product quality. However, a correlation between the results of these controls and the RPN values, looking at the risk of non-sterility, is difficult to prove.

What this paper adds

What is already known on this subject?

- ⇒ Aseptic handling has to be executed with aseptic precautions in a laminar airflow cabinet, safety cabinet or isolator.
- \Rightarrow The operator is the highest source of risk of non-sterility.

What does this study adds?

- ⇒ Risks of non-sterility and measures to reduce it can be objectified by a risk assessment and risk control model.
- ⇒ Of all risk reducing measures, a yearly audit of all operators has the greatest impact on reducing the risk of non-sterility.
- ⇒ The results of microbiological controls are less useful for assessing the risk of non-sterility.

Contributors The first author did the experimental work and wrote the draft text. The other authors participated in the design and review of the study.

Funding The authors have not declared a specific grant for this research from any funding agency in the public, commercial or not-for-profit sectors.

Competing interests None declared.

Patient consent for publication Not required.

Provenance and peer review Not commissioned; externally peer reviewed.

Data availability statement All data relevant to the study are included in the article or uploaded as supplementary information.

Supplemental material This content has been supplied by the author(s). It has not been vetted by BMJ Publishing Group Limited (BMJ) and may not have been peer-reviewed. Any opinions or recommendations discussed are solely those of the author(s) and are not endorsed by BMJ. BMJ disclaims all liability and responsibility arising from any reliance placed on the content. Where the content includes any translated material, BMJ does not warrant the accuracy and reliability of the translations (including but not limited to local regulations, clinical guidelines, terminology, drug names and drug dosages), and is not responsible for any error and/or omissions arising from translation and adaptation or otherwise.

Open access This is an open access article distributed in accordance with the Creative Commons Attribution 4.0 Unported (CC BY 4.0) license, which permits others to copy, redistribute, remix, transform and build upon this work for any purpose, provided the original work is properly cited, a link to the licence is given, and indication of whether changes were made. See: https://creativecommons.org/ licenses/by/4.0/.

REFERENCES

- 1 Resolution CM/Res(2016)2 on good reconstitution practices in health care establishments for medicinal products for parenteral use. Available: https://www. edqm.eu/sites/default/files/resolution_cm_res_2016_2_good_reconstitution_ practices_in_health_care_establishments_for_medicinal_products_for_parenteral_ use_.pdf [Accessed 15 Jan 2021].
- 2 Thompson RW, Belisle C. Respecting the risks of sterile compounding. Am J Health Syst Pharm 2015;72:1269.
- 3 Larmené-Beld KHM, Frijlink HW, Taxis K. A systematic review and meta-analysis of microbial contamination of parenteral medication prepared in a clinical versus pharmacy environment. *Eur J Clin Pharmacol* 2019;75:609–17.
- 4 Boom FA, Ris JM, Veenbaas T, et al. Reducing the risk of non-sterility of aseptic handling in hospital pharmacies, part A: risk assessment. Eur J Hosp Pharm 2022;29:151–6.
- 5 Boom FA, Ris JM, Veenbaas T, et al. Reducing the risk of non-sterility of aseptic handling in hospital pharmacies, part B: risk control. Eur J Hosp Pharm 2021;28:325–30.
- 6 Dutch association of hospital pharmacists. Z3 aseptic handling. In GMP-Hospital pharmacy, 2013. Available: https://nvza.nl/wp-content/uploads/2016/04/Z3-GMPZ_ Herziening-2013-Z3-Aseptische-handelingen-def-IGZ.pdf [Accessed 15 Jan 2021].
- 7 Royal Dutch Pharmacists Association. LNA-procedure Validatie aseptische werkwijze, 2010. Available: https://kennisbank.knmp.nl/ [Accessed 15 Jan 2021].
- 8 Boom FA, Brun PPHL, Bühringer S, et al. Microbiological monitoring during aseptic handling: methods, limits and interpretation of results. Eur J Pharm

Original research

Sci 2020;155:105540 https://www.sciencedirect.com/science/article/pii/ S0928098720303286

- 9 QuickCalcs G. Fisher's and chi-square. Analyze a 2x2 contingency table. Available: https:// https://www.graphpad.com/quickcalcs/contingency1/ [Accessed 15 Jan 2021].
- 10 Royal Dutch Pharmacists Association. LNA-procedure Microbiologische monitoring, opstellen bemonsteringsplan en beoordelen van de resultaten, 2019. Available: https://kennisbank.knmp.nl/ [Accessed 15 Jan 2021].
- 11 YouTube. Keep critical spots in first air. Available: https://www.youtube.com/channel/ UCYicF1ULbvVkniF3Hr0gCyA?view_as=subscriber [Accessed 15 Jan 2021].
- 12 Boom FA, Le Brun PPH, Boehringer S. Improving the aseptic transfer procedures in hospital pharmacies Part C: evaluation and redesign of the transfer process., 2019. Available: https://ejhp.bmj.com/content/early/2019/10/29/ejhpharm-2019-002034 [Accessed 15 Jan 2021].
- 13 Boom FA, Le Brun PPH, Boehringer S. Improving the aseptic transfer procedures in hospital pharmacies Part B: disinfection methods for materials with a non-sterile surface. published online by EU J Hosp pharm, 2019. Available: https://ejhp.bmj.com/ content/early/2019/08/24/ejhpharm-2018-001673 [Accessed 15 Jan 2021].
- 14 Beaney AM. Quality assurance of aseptic preparation services: standards handbook. UK: Pharmaceutical Press, 2016.
- 15 Eu good manufacturing practice (GMP) Annex 1 2nd revision. manufacture of sterile medicinal products, 2020. Available: https://ec.europa.eu/health/sites/health/files/ files/gmp/2020_annex1ps_sterile_medicinal_products_en.pdf [Accessed 15 Jan 2021].

- 16 Boom FA, Le Brun PPH, Boehringer S, et al. Improving the aseptic transfer procedures in hospital pharmacies Part A: methods for the determination of the surface bioburden on ampoules and vials. Eur J Hosp Pharm 2021;28:38–41.
- 17 Royal Dutch Association of Pharmacists. LNA-procedure Microbiologische monitoring, uitvoering monstername, 2019. Available: https://kennisbank.knmp.nl/ [Accessed 15 Jan 2021].
- 18 Parenteral Drug Association. *Technical report no. 44: quality risk management for aseptic processing*. Parenteral Drug Association, 2008.
- 19 Bouwman-Boer Y, Møller Andersen A. Pharmaceutical quality system. In: Bouwman-Boer Y, Fenton-May V, le Brun PPH, eds. *Practical pharmaceutics*. Switzerland: Springer International Publishing, 2015: 769–96.
- 20 Tidswel EC, Boone K. Environmental and personnel monitoring programs -a risk-based case study of *cutibacterium acnes*. *PDA J Pharm Sci Technol* 2020;74:408–22.
- 21 EU GMP chapter 1. the rules governing medicinal products in the European union. EU legislation - eudralex -volume 4 good manufacturing practice (GMP) guidelines. chapter 1. pharmaceutical quality system, 2013. Available: https://ec.europa.eu/ health/sites/health/files/files/eudralex/vol-4/vol4-chap1_2013-01_en.pdf [Accessed 15 Jan 2021].
- 22 EU GMP Annex 1. The rules governing medicinal products in the European Union. EU legislation eudralex -volume 4 good manufacturing practice (GMP) guidelines. Annex I. manufacture of sterile medicinal products, 2009. Available: https://ec.europa.eu/health/sites/health/files/files/eudralex/vol-4/2008_11_25_gmp-an1_en.pdf [Accessed 15 Jan 2021].